

# Kneehill Area Solid Waste Transfer Station Facilities

## Where should I go for...?

### Acme\*

SW 19-29-25-W4  
Tuesday & Thursday  
10 am - 5 pm  
Saturday  
9 am - 5pm

### Carbon

NW 13-29-23-W4  
Saturday  
9 am - 5pm

### Kneehill County

(Torrington Site)  
SW 20-32-26-W4  
Wednesday  
10 am - 6 pm  
Saturday  
10 am - 6 pm

### Linden

NW 19-30-25-W4  
Tuesday & Thursday  
10 am - 6 pm  
Saturday  
9 am - 5pm

### Three Hills

SW 25-31-24-W4  
Tuesday & Thursday  
10 am - 6 pm  
Saturday  
9 am - 5pm

### Trochu\*

NE 16-33-23-W4  
Thursday  
1pm - 5 pm  
Friday & Saturday  
9 am - 5 pm



#### Transtor Bins

Acme, Carbon, Linden, Torrington  
Three Hills & Trochu Transfer Sites



#### Batteries

Carbon, Linden, Three Hills,  
Torrington & Trochu Transfer Sites



#### Dry Rubble

Torrington Transfer Site




#### Pesticide Containers

Three Hills Transfer Site




#### Scrap Metal

Linden, Trochu & Torrington Transfer Sites



#### Twine

Three Hills Transfer Site



#### White Metal

Linden, Torrington & Trochu Transfer Sites




#### Burning Pit

Linden, Torrington & Trochu Transfer Sites



#### Wire

Linden & Torrington Transfer Sites



#### Paint Cans

Linden, Three Hills,  
Torrington & Trochu Transfer Sites



#### Tires

Linden, Torrington & Trochu Transfer Sites



#### Electronic Waste

Linden, Torrington,  
& Trochu Transfer Sites

\* Please visit Acme and Trochu's website for the latest information on these transfer sites.

**Attendants have the right to reject loads based on material, type, volume, source, prevailing weather or any factor affecting disposal facility operation.**